



EQUIPMENT COMPANY




TIMING CHART FOR 24.9% AS SEEN FROM CLUTCH PACK END

LENCO


EQUIPMENT COMPANY




TIMING CHART FOR 16.2% AS SEEN FROM CLUTCH PACK END



EQUIPMENT COMPANY




TIMING CHART FOR 23% DOUBLE GEAR SET
AS SEEN FROM CLUTCH PACK END




TIMING CHART FOR 22.4% AS SEEN FROM CLUTCH PACK END


LENCO EQUIPMENT COMPANY




TIMING CHART FOR 21.4% AS SEEN FROM CLUTCH PACK END




EQUIPMENT COMPANY



TIMING CHART FOR 19.9% AS SEEN FROM CLUTCH PACK END



EQUIPMENT COMPANY



TIMING CHART FOR 18.4% AS SEEN FROM CLUTCH PACK END